

General Environmental Incident Summary

Incident: 3608 **Date/Time Notice:** 1/14/2015 1800 **DEM Incident No:**
Responsible Party: WCE Oil Field Services
Date Incident: 1/13/2015 **Time Incident:** 1500 **Duration:** 5 minutes
County: McKenzie **Twp:** 149 **Rng:** 99 **Sec:** 26 **Qtr:** SE
Lat: 47.69601 **Long:** -103.31200 **Method:** Navigation quality GPS
Location Description: Location is on active pipeline construction ROW (ONEOK) and is accessed via marked entrances along county road.
Submitted By: Todd Kelvington **Affiliation:** ONEOK
Address: 100 West Fifth Street
City: Tulsa **State:** OK **Zip:** 74103

Received By:

Contact Person: Tim Lengquist
208 N. Main Street
Stanley , ND 58784

Distance Nearest Occupied Building: 1.5 Miles **Release Contained:** Yes

Type of Incident: construction equipment failure

Description of Released Contaminant: Hydraulic fluid

Volume Spilled: 20.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Hydraulic line rupture on pipeline construction equipment

Risk Evaluation:

No immediate risks. Impacted material was contained and excavated.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Minimal risk of residual soil impacts. No direct impacts to surface waters or sensitive features.

Action Taken or Planned:

Spill area was treated with absorbant spill kits and impacted material was excavated.

Wastes Disposal Location: Clean Energy, Watford City ND

Agencies Involved:

Updates

Date: 1/14/2015 ***Status:*** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

Description of release and cleanup of hydraulic fluid on pipeline construction right-of-way adequate.
No on-site inspection necessary.